

### UNIVERSAL INPUT

SENSOR		
J	- □ -	600° C
K	- □ -	1200° C
PT-100	- □ -	399.9° C

