


DA

HUMIDITY SENSOR

SSR

RTD SENSOR



BK BL BR

- 0/P +

W W R

**AUX SUPPLY
220 VAC**

TEMPERATURE HUMIDITY

NC C NO NC C NO

